

Reeling



The yarns on cones collected must be prepared for the mercerization of making hanks, this process is



The hank is tied with three or more ties or Bandoli, these should be of a material inert to hydroxide cause

The formation of the hanks must be provided to facilitate the addition of sodium hydroxide until the centr